



https://zoomcorp.com/

Version 2.40

- · Release to fix the following issue in October 2024
- 1. If recording was started after moving the playback position to a marker, the region being recorded would sometimes disappear.

Version 2.30

- Release to fix the following issues in September 2023
- 1. Rhythm track loops would not play in rare cases.
- 2. After a track type was changed from synth to audio once, synth sounds would not be output.
- After swapping stereo and mono tracks, when mono tracks were recorded, they would be recorded as stereo.
- After swapping stereo and mono tracks, unintended effects would sometimes be applied to other tracks.
- 5. After swapping stereo and mono tracks, stereo tracks would sometimes play back at half speed.
- After swapping tracks, during playback, other regions would play back repeatedly in parts without regions.
- After moving a mono region to a different track, if a stereo region was added to the track where it had been, the waveform would sometimes not be shown correctly.
- 8. After pressing the REC button during recording to switch to playback, pressing the FF/REW button would not update the display.

Version 2.10

- Release to fix the following issue in July 2023
- 1. When recording with a project that had a bit depth of 24-bit, the recording data could be damaged.

Version 2.00

- Release to add the following function in March 2023
- Support has been added for the dedicated R12 Control app, which enables control of the R12 from an iPad.

Version 1.00

Released as mass production in September 2022