

Precaution with attaching products to tripod heads

If a tripod head that has a gap around the screw is used, more force than is necessary could be applied to the screw hole (tripod mounting threads), resulting in damage, when the product is attached. We recommend being careful not to over-tighten the connection or using a tripod head that does not have a gap around the screw.



Tripod without gap around screw



Tripod with gap around screw

